

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	1	"6468605"	USPAT	2004/10 /08 08:48			0
2	IS&R	L2	4	("6468605") or ("6224985") or ("5894403") or ("5920455")).PN.	USPAT	2004/10 /08 08:51			0
3	BRS	L3	5358 53	capacitor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10 /08 08:52			0
4	BRS	L4	9346	feedthrough	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10 /08 08:52			0
5	BRS	L5	2706	3 and 4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10 /08 08:52			0
6	BRS	L6	218	casing and 5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10 /08 09:09			0
7	BRS	L7	3309 72	bridge	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10 /08 09:09			0
8	BRS	L8	4570 1	3 and 7	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10 /08 09:10			0
9	BRS	L9	5143	("361/500-540").cc ls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10 /08 09:15			0
10	BRS	L10	106	8 and 9	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10 /08 09:11			0
11	BRS	L11	701	361/302	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10 /08 09:16			0